



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

February 26, 2007

Supervisor DRZ

**Mine Name:** Green Peak Quarry  
**Operator Name:** I & P Investments, Inc.

**Permit number:** M0030060  
**Inspection Date:** November 21, 2006  
**Time:** 1:00 pm

**Inspector(s):** Lynn Kunzler, DOGM  
**Other Participants:** none  
**Mine Status:** Permitted, no recent activity

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

Document site conditions at the work area.

#### Inspection Summary:

1. There has been no apparent activity this year. Of concern with the work area, the Division had received a phone call indicating that this was located on mining claims not under the control of the operator. During this inspection it was documented that there was no rock quarrying operation on this part of the permit. The only observed disturbances at this site appears to be related to topsoil salvage, waste rock disposal, splitting/palleting stone and equipment/material storage. Photos were taken to document this disturbance, as well as adjacent areas to demonstrate the lack of 'claimable' rock.

The quarry and millsite area associated with this permit were also visited. There has been no activity within recent weeks/months at either of these sites. All three areas appeared to be stable, there were no debris or erosion problems noted.

#### Conclusions and Recommendations:

1. Continue to monitor this site when in the area.

Inspector's Signature

LK:pb

O:\M003-BoxElder\M0030060-GreenPeak\inspections\Insp-11212006.doc